



Packing List
HS 200E System
8007-0232

	QTY	PART NUMBER	
POWER SOURCE,PPS28 230V	1	7008-0216-02	<input type="checkbox"/>
POWER CORD,DETACHABLE,230V	1	1332-0093	<input type="checkbox"/>
PLATE,SHIELD	1	1335-0227	<input type="checkbox"/>
TAG, LINE CORD, EXPORT	1	1351-0191	<input type="checkbox"/>
ASSY,HEATER UNIT,230V	1	6010-0090-02	<input type="checkbox"/>
KIT, HEATWAVE BRD HOLDER	1	6993-0197-P1	<input type="checkbox"/>
HANDPIECE, PV-65, PIK-VAC	1	7027-0001-P1	<input type="checkbox"/>
CD,PACE MANUALS 5 LANG.	1	CD5050-0459	<input type="checkbox"/>
KIT,ACCESS,HS200	1	7950-0127	<input type="checkbox"/>
SCREWDRIVER, PACE	1	1100-0230	<input type="checkbox"/>
KNOB,THUMBSCREW#10-32X.37LG	2	1222-0098	<input type="checkbox"/>
KNOB,THUMBSCREW 10-32X1.50	1	1222-0103	<input type="checkbox"/>
BRACKET,ARM SUPPORT,LONG	1	1257-0205	<input type="checkbox"/>
ARM,ADJUSTABLE,SHORT	1	1257-0206	<input type="checkbox"/>
BRACKET,ARM SUPPORT,SHORT	1	1257-0207	<input type="checkbox"/>
ARM,ADJUSTABLE,LONG	1	1257-0208	<input type="checkbox"/>
DISCONNECT,QUICK,MALE,HOSE	2	1259-0087	<input type="checkbox"/>
PAD, S/S ADH.,1.00X.24X.06	4	1317-0031	<input type="checkbox"/>
HOLDER, TUBE/WIRE,BLK PK6	1	1321-0085-01-P6	<input type="checkbox"/>
ASSY, INTERFACE CABLE	1	1332-0187	<input type="checkbox"/>
HOT PLATE, 5.5 SQ	1	1335-0177	<input type="checkbox"/>
TUBING,SIL.,.125ID,54L,BLK	1	1342-0015-08	<input type="checkbox"/>
SCR,FLT,6-32X.31,SSNASL	2	1405-0668	<input type="checkbox"/>
SCR,PAN,6-32X.38,SSNACR	4	1405-0670	<input type="checkbox"/>
WASHER,FLAT,5/8OD X .195ID	2	1415-0073	<input type="checkbox"/>