



Packing List
XR 4000 W/PC
8007-0400-01

	QTY	PART NUMBER	
FINAL ASSEMBLY, XR4000	1	7008-0251	
ASSY, CABLE, COAXIAL/BNC	1	1107-0014	
FRAME GRABBER	1	1193-0115	
ANALYTICAL SOFTWARE	1	1199-0009	
BRACKET, LT, MOUNT, COMPUTER	1	1257-0324	
BRACKET, RT, MOUNT, COMPUTER	1	1257-0325	
POWER CORD,DETACHABLE,230V	1	1332-0093	
EXTERNAL VIDEO CABLE	1	3008-0168	
SCR,BTN,10-32X.50,SSNAHS	4	1402-0067	
COMPUTER, 2.0 GHZ P4	1	6020-0176	
FLAT SCREEN MONITOR	1	7015-0010	
CD,PACE MANUALS 5 LANG.	1	CD5050-0459	